



RECTRON

RECTIFIER SPECIALISTS

Tel : (021)5814-3456 Fax: (021)5814-3561

To : All Sales office

FM: AE

Date : 2006,Jun,6

Subject: Change notice for leads plating method of RB15

1. Due to lead supplier will be stopped to supply the currently silver plated lead.
2. Rectron would like to change the lead plating method from silver plating to 100% tin plating.
3. The new plating method (100% Tin) would not affect the solderability and no need to change the soldering profile of customer side.
4. The tin plating goods also 100% compliance RoHS requirement
5. The effect P/N including to RB151 thru RB157
6. The effective date from 2006, Aug, 1st
7. If the customer need the sample for re-approve, Pls. advice AE

Manager of AE Dept.

Richard Liu